



## Rust Bullet Rapid Fire

Directions for Use: Rust Bullet® Coatings accelerated with Rapid Fire are designed for spray application. Open the Rust Bullet Coating and stir thoroughly to incorporate any settling or separation before adding Rapid Fire Accelerator. Add the pre-measured amount of Rapid Fire Accelerator to the thoroughly stirred Rust Bullet coating and stir only enough to incorporate the accelerator into the coating. Rapid Fire reduces the drying time of Rust Bullet and Rust Bullet Automotive from 4 hours to 30 minutes and reduces the drying time for Rust Bullet BlackShell™ from 8 hours to 1 hour. Once Rapid Fire Accelerator has been added to any Rust Bullet coating, there will be a pot-life. Immediately after Rapid Fire has been combined with the coating, put a thin solvent float of Xylene or Toluene over the top of the coating in the container. Keep container closed when not in use. Accelerate only the materials that will be used in a 6 hour period.

Obtain the Rust Bullet Rapid Fire Data Sheet and MSDS for complete product description, application directions, and safety information.

Rust Bullet, LLC

300 Brinkby Ave., Suite 200, Reno, NV 89509, USA

Rust Bullet® is a Registered Trademark.

**DANGER! COMBUSTIBLE LIQUID AND VAPOR  
CAUSES EYE IRRITATION. CAUSES SKIN BURNS. HARMFUL IF SWALLOWED.  
KEEP OUT OF REACH OF CHILDREN**

**DANGER!  
CORROSIVE**

**DANGER: CORROSIVE** Causes skin and eye burns. Causes nose, throat and lung irritation. Harmful if swallowed. Vapor harmful. May affect the brain or nervous system causing dizziness, headache, or nausea. **NOTICE:** Reports have associated repeated and prolonged occupational over exposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling contents may be harmful or fatal. Combustible liquid. Forms combustible mixtures with air at or above the flash point. Keep away from heat, sparks and flame. Vapor may cause flash fire. Do not smoke. Extinguish all flames and pilot lights, and turn off all stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Prevent build up of vapors by opening all windows and doors to achieve cross ventilation. Use Only With Adequate Ventilation and Personal Protection. Do not breathe dust, vapors or spray mist. Ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH approved) during and after application. Follow respirator manufacturer's directions for respirator use. Do not get in eyes, on skin or clothing. Wash thoroughly after handling. **FIRST AID:** In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention; for skin, wash thoroughly with soap and water. Get medical attention if irritation persists. If affected by inhalation of vapor or spray mist, remove to fresh air; get medical attention immediately. If swallowed, do not induce vomiting; get medical attention immediately. Remove contaminated clothing and shoes. Destroy or thoroughly clean contaminated clothing or shoes before reuse. Keep container closed when not in use. If spilled, prevent bodily contact. Contain spilled material and remove with inert absorbent.

Rust Bullet, LLC

300 Brinkby Avenue, Suite 200 ~ Reno, Nevada 89509 ~ USA

800-245-1600

[www.RustBullet.com](http://www.RustBullet.com)